



402915

D.6

(Y) Person(s) Interviewed

Title

Telephone

R. A. HeinemannMgr. Facility Environment313 285-9200Jack LewisEnergy EnvironmentDr. John PoulosMgr. Laboratory

(Z) Inspection Participants

Agency/Title

Telephone

David YanochkoMDNR Environmental Engineer 517/373-2508Sam NortonMDNR Water Quality Specialist 313/379-9672

(A) Preparer Information

Name

Agency/Title

Telephone

David YanochkoMDNR Environmental Engineer 517/373-2508II. SITE ACTIVITY:

Complete sections I through VII for all treatment, storage, and/or disposal facilities. Complete the forms (in parenthesis) in section VIII corresponding to the site activities identified below:

A. Storage and/or Treatment

1. Containers (I)
2. Tanks (J)
3. Surface Impoundments (K)
4. Waste Piles (L)

B. Land Treatment (M)C. Landfills (N)D. Incineration and/or Thermal Treatment (O and P)E. Chemical, Physical, and Biological Treatment (Q)

Note: If facility is also a generator or transporter of hazardous waste complete sections IX and X of this form as appropriate.

III. GENERAL FACILITY STANDARDS:
(Part 265 Subpart B)

	Yes	No	NI*	Remark
(A) Has the Regional Administrator been notified regarding:				
1. Receipt of hazardous waste from a foreign source? 265.12(a)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>None Received</u>
2. Facility expansion? 122.23(b)2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>None Planned</u>
(b) General Waste Analysis:				
1. Has the owner or operator obtained a detailed chemical and physical analysis of the waste? 265.13(a)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2. Does the owner or operator have detailed waste analysis plan on file at the facility? 265.13(b)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3. Does the waste analysis plan specify procedures for inspection and analysis of each movement of hazardous waste from off-site? 265.13(c)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>No wastes received from off-site sources</u>
(C) Security - Do security measures include: (if applicable) 265.14				
1. 24-Hour surveillance? 265.14(b)1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2. Artificial or natural barrier around facility? 265.14(b)2	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>fenced all sides except Detroit River</u>
3. Controlled entry? 265.14(b)2ii	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4. Danger sign(s) at entrance? 265.14(c)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>Signs completely around facility on fence</u>
(D) Do Owner or Operator Inspections Include: 265.15				
1. Records of malfunctions? 265.15(a)1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>DNR Spill Report Forms</u>
2. Records of operator error? 265.15(a)1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3. Records of discharges? 265.15(a)1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

*Not Inspected

ENVIRONMENTAL PROTECTION AGENCY
NOTIS DATA MANAGEMENT SYSTEM

NOTIS REPORT #4

LISTING BY FACILITY
REGION: 05 STATE: MI

PAGE: 181
REPORT DATE: 10/14/81

NOTIFICATION ID NO.	SITE NAME SITE STREET SITE CITY SITE COUNTY EPA SITE ID NO.	NOTIFIER NAME NOTIFIER STREET NOTIFIER CITY (CONTACT NAME/TITLE) (CONTACT PHONE)	STATE	ZIP	NOTIFIER STATUS (PRES OWN, PAST OWN, PRES OP, PAST OP, TRANSPORTER, VOLUNTEER)
MI0000001175	PENNWALT CORPORATION 4655 BIDDLE AVE. WYANDOTTE WAYNE MID005363114	JOHN BOGREN, PLANT MANAGER 4655 BIDDLE AVENUE WYANDOTTE (HEINEMAN, ROBERT - MGR. ENERGY SERV) (313-285-9200)	MI	48192	PRES OWN

RELEASES TO THE ENVIRONMENT:

DATES OF WASTE HANDLING: 1904 TO 1979

WASTE AMOUNT: 340,000 CU FT APPR: 70,000 SQ FT MAP PRESENT: NO PCB TYPE: 8900-1

NOTIF. POSTMARKED DATE: 81/06/08 SIGNATURE PRESENT: YES DATE OF LAST UPDATE: 81/09/25

TYPE OF FACILITY	TYPE OF WASTE	SOURCES OF WASTE
OTHER (SEE COMMENTS) IMPOUNDMENT DRUM BELOW GROUND LANDFILL	ORGANICS INORGANICS UNKNOWN OTHER	CHEMICALS, GENERAL PLATING/POLISHING

COMMENTS

SEQ NO.

LENGTHLY SEE FILE

1

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

810608

MI #203

MIS-000-001-175

A Person Required to Notify:

Enter the name and address of the person or organization required to notify

Name Pennwalt Corporation - Wyandotte Plant

Street 4655 Biddle Avenue

City Wyandotte State MI Zip Code 48192

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Pennwalt Corporation - Wyandotte PLANT

Street 4655 Biddle Avenue

City Wyandotte County Wayne State MI Zip Code 48192

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Heineman, Robert - Mgr. Energy & Environmental

Phone (313) 285-9200, ext. 365

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1904 To (Year) 1978

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☒ Organics
2. ☒ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☒ Unknown
11. ☐ Other (Specify)

Source of Waste:
Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☒ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

JUN 12 1981

000198 JUN-8 81

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☒ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☒ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amountcubic feet 350,000 ☒

gallons _____

Total Facility Areasquare feet 70,000 ☒

acres _____

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ None

not known

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

This site contains chemical manufacturing facilities, both inorganic (begun 1898) and organic (begun 1932). It is located within the city boundaries of Riverview and Wyandotte, Michigan. The site is bounded by other industry on the North and South, the Detroit River on the East and by a Railroad and Utility right-of-way and Pennwalt non-contiguous property on the West. No water wells are known to exist in the vicinity.

The bulk of wastes covered by this notification are not considered hazardous by RCRA criteria to the best of our knowledge. No hazardous wastes are currently disposed of on this site.

This location has currently on-site an active storage facility for PCB items. This storage area of approximately 600 sq. ft. currently contains some 700 gallons of PCB liquid. Design and construction of this storage facility is in accordance with current published Regulations under TSCA and has been inspected by EPA.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name John Bogen, Plant Manager

Street 4655 Biddle Avenue

City Wyandotte

State MI Zip Code 48192

Signature

John Bogen

Date 6/8/81

☒ Owner, Present☐ Owner, Past☐ Transporter☐ Operator, Present☐ Operator, Past☐ Other